



CRAIGFORTH NEAR STIRLING, UNITED KINGDOM

Rockfall Protection

Craigforth near Stirling

Rockfall Protection

Project	Craigforth near Stirling
Location	Craigforth near Stirling
Country	United Kingdom
Year of installation	2010
Customer	Prudential Financial Inc.
Engineering	BAM Ritchies / FES FM Ltd.
Contractor	BAM Ritchies / BAM Nuttal Ltd.
Initial situation	The car park of the site is occasionally struck by small rockfall from crags that form the boundary of the site.
Description	To protect the car park and building on the site from damage a continuing process of assesment and mitigation is on going. To date GBE-500A-R and GBE-100A-R rockfall barriers have been built on site with further fences planned for upcoming years.
Protected object	Road, Building
Corrosion protection	Galvanized, GEOBRUGG SUPERCOATING
Energy absorption capacity	100 kJ, 500 kJ
System height	2.0 m, 3.0 m
System length	300 m - 300 m

For questions please contact our Geobrugg specialist at your side

Kevin H. Coyle

Regional Manager Northeast

Phone +1 860 377 3230

kevin.coyle@geobrugg.com



Geobrugg

info@geobrugg.com | www.geobrugg.com
