



# PEÑON DEL CORTIJO, COLOMBIA

**Slope Stability**

# Peñon del Cortijo

## Slope Stability

<b>Project</b>	Peñon del Cortijo
<b>Location</b>	Bogotá
<b>Country</b>	Colombia
<b>Year of installation</b>	2015
<b>Customer</b>	n/a
<b>Engineering</b>	Constructora Jeinco
<b>Initial situation</b>	n/a
<b>Description</b>	n/a
<b>Protected object</b>	Building
<b>Corrosion protection</b>	GEOBRUGG SUPERCOATING
<b>Stabilized area</b>	11000 m <sup>2</sup>
<b>Greening</b>	Yes
<b>Exposition</b>	North

For questions please contact our Geobrugg specialist at your side

---

### Kevin H. Coyle

Regional Manager Northeast

Phone +1 860 377 3230

[kevin.coyle@geobrugg.com](mailto:kevin.coyle@geobrugg.com)



### Geobrugg

[info@geobrugg.com](mailto:info@geobrugg.com) | [www.geobrugg.com](http://www.geobrugg.com)