



# SLOPE STABILIZATION ON THE CASTLE HILL, POLAND

Slope Stability

# Slope stabilization on the Castle Hill

## Slope Stability

<b>Project</b>	Slope stabilization on the Castle Hill
<b>Location</b>	Sandomierz
<b>Country</b>	Poland
<b>Year of installation</b>	2011
<b>Customer</b>	Town council
<b>Engineering</b>	GEOREM Sp. z o.o.
<b>Contractor</b>	GEOREM Sp. z o.o.
<b>Initial situation</b>	-
<b>Description</b>	-
<b>Protected object</b>	Building
<b>Corrosion protection</b>	GEOBRUGG SUPERCOATING
<b>Stabilized area</b>	430 m <sup>2</sup>
<b>Maximum slope height</b>	16 m
<b>Slope inclination</b>	40 ° - 45 °
<b>Greening</b>	Yes
<b>Erosion control mat</b>	Yes
<b>Exposition</b>	

**For questions please contact our Geobrugg specialist at your side**

---

**Kevin H. Coyle**

Regional Manager Northeast

Phone +1 860 377 3230

kevin.coyle@geobrugg.com



**Geobrugg**

info@geobrugg.com | www.geobrugg.com

---