



COCKERMOUTH CASTLE, REINO UNIDO

Estabilização de taludes

Cockermouth Castle

Estabilização de taludes

Projeto	Cockermouth Castle
Lugar	Cockermouth
País	Reino Unido
Ano de instalação	2016
Promotor	Cockermouth Castle
Contratante	CAN Geotechnical
Situação inicial	Following heavy storms and flooding in 2015 significant erosion was caused to the riverbank under the castle.
Descrição	In conjunction with the geotechnical contractor, who had already decided the slope needed soil nailing and TECCO® System, we looked to optimise the solution for the fine grained nature of the soil. We suggested the use of the TECCO® G45/2 in conjunction with an erosion control mat.
Objecto protegido	Infra-estrutura turística, Outros
Proteção contra a corrosão	GEOBRUGG SUPERCOATING
Geologia	Quaternary fluvial sands.
Área estabilizada	840 m ²
Altura do talude	20 m
Geomalha de controlo de erosão	Sim
Exposição	-

Em caso de dúvidas por favor contacte com nosso especialista Geobrugg na sua área

Roger Moor

Country Manager Ost- und Zentralschweiz, Liechtenstein

Telefone+41 71 466 81 52

Telemóvel+41 78 783 46 81

Roger.Moor@geobrugg.com



Geobrugg

info@geobrugg.com | www.geobrugg.com
