



JJ RONDON, COLUMBIA

Stabilizarea pantelor

JJ Rondon

Stabilizarea pantelor

Proiect	JJ Rondon
Loc	Bogota
Țară	Columbia
Anul instalării	2015
Client	Alcaldia Local de Ciudad Bolivar
Tehnologie	Geocing
Antreprenor	Constructora Jeinco
Situația inițială	An access road to the neighborhood was cut into a subsoil of residual soils and layers of highly fractured and weathered sandstones.
Descriere	TECCO® G65/3 in combination with TECMAT® was installed to stabilize the area and protect people using the road. The solution is a long-term protection for people and infrastructure.
Obiect protejat	Road, Clădire, Residential area
Protecție împotriva coroziunii	GEOBRUGG SUPERCOATING
Zonă stabilizată	700 m²
Înălțime pantă	10 m
Înclinație pantă	60 ° - 85 °
Vegetație	Da
Rețea de control a eroziunii	Da
Expoziție	Nord

Pentru întrebări, vă rugăm să contactați specialistul Geobrugg din zona dvs.

Roger Moor

Country Manager Ost- und Zentralschweiz, Liechtenstein

Telefon +41 71 466 81 52

Mobil +41 78 783 46 81

Roger.Moor@geobrugg.com



Geobrugg

info@geobrugg.com | www.geobrugg.com
